

FIG. 1




FIG. 2 (a)




FIG. 2 (b)




FIG. 3




FIG. 4




FIG. 5 (a)




FIG. 5 (b)




FIG. 6 (a)




FIG. 6 (b)




FIG. 7 (a) PRIOR ART




FIG. 7 (b) PRIOR ART




FIG.8 PRIOR ART




FIG.9 PRIOR ART




Figure 1 is a schematic diagram of a measurement system. At the top, a point source (2) emits four rays through a rectangular frame (10). The frame has four sensors (11) at its corners. The frame is mounted on a base (4). Below the base, a circular cross-section shows concentric rings (12x, 11x) and a central point (11x).